



		Debris Flow Hazard		
		Low	Moderate	High
Landslide Hazard	High	H3	H2	H1
	Moderate	M1	M3	H5
	Low to Very Low	L1	M2	H4

**Legend**

- H1
- H2
- H3
- H4
- H5
- L1
- M1
- M2
- M3

Aerial Photography flown between 2001 and 2007, depending on the area. Parcel boundaries are to be taken as approximate only, not to be substituted for site specific survey. May contain LINZ data: Crown Copyright Reserved. Note: Placenames may not conform to LINZ guidelines 2008. DISCLAIMER: While Whakatane District Council (WDC), has exercised all reasonable skill and care in controlling the contents of this information, WDC accepts no liability in contract, tort or otherwise howsoever, for any loss, damage, injury or expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you. \*Position of all assets & historical sites are approximate, actual positions are to be verified on site.